

# Visual Installation Instructions

## FuseLite® Single-Fiber Connector SRP

### Table of Contents

1. Connectors

1	FuseLite® SC/LC Connectors on 250-900 µm Tight-Buffered Fiber .....	1
2	FuseLite SC/LC Connectors on Buffer Tube Fan-Out Kits.....	6
3	FuseLite SC/LC Connectors on Jacketed Cable (2.0/3.0 mm) .....	11
4	Safety Precautions .....	18

# Visual Installation Instructions

## FuseLite® SC/LC Connectors on 250-900 $\mu\text{m}$ Tight-Buffered Fiber

### Tools Required

SC or LC FuseLite® Connectors  
Fusion Splicer (OptiSplice® Ribbon Fusion Splicer Shown Here)  
Connector Holder (SOC-HLD-CON-SCLC)  
Fiber Holder (SOC-HLD-900-OS)  
Cleaver  
Dual-Hole Miller Tool  
Fiber Optic Cleaning Fluid  
Lint-Free Wipes  
Permanent Marker

1

SC



For SC FuseLite® Connector,  
Go to Step 1A

LC




For LC FuseLite Connector,  
Go to Step 1B

OR

1A


SC



Insert Rear SC Housing and Protection Sleeve  
onto the Field Fiber. Proceed to Step 2

1B

LC



Insert Rear LC Housing and Protection Sleeve  
onto the Field Fiber. Proceed to Step 2


2

900  $\mu\text{m}$  250  $\mu\text{m}$




Two-Hole Miller Stripper (900  $\mu\text{m}$  and 250  $\mu\text{m}$ )

3




Place a Mark  $\geq 40$  mm from the End of the Fiber

4



Strip the 900  $\mu\text{m}$  Buffer with Larger Notch


5



Strip the 250  $\mu\text{m}$  Coating with the Smaller Notch


## Visual Installation Instructions

### FuseLite® SC/LC Connectors on 250-900 $\mu\text{m}$ Tight-Buffered Fiber




**6**

Moisten Wipe with Fiber Cleaning Fluid




**7**

Clean with Fiber Solution (Wipe Twice)




**8**

Place Field Fiber in the Holder Groove  
Align 900  $\mu\text{m}$  Buffer Flush with Raised Channel




**9**

Close Fiber Holder (SOC-HLD-900-OS) Lid, Keeping Fiber in Place




**10**

Place Holder in Cleaver and Slide to the Right Until It Hits the Positive Stop




**11**

Gently Press Down the Lever Until It Stops, Then Release




**12**

Load the Fiber Holder into the Splicer (on the Right Side)



**13**


Fiber Should Be in "V-Groove"



**14**


Connector Holder

Ferrule Assembly



**15**

Load Ferrule Assembly into the Connector Holder; Dot Facing Out









**16**

Close the Holder Arm






## Visual Installation Instructions

### FuseLite® SC/LC Connectors on 250-900 $\mu\text{m}$ Tight-Buffered Fiber



## Visual Installation Instructions

### FuseLite® SC/LC Connectors on 250-900 $\mu\text{m}$ Tight-Buffered Fiber






CORNING



## Visual Installation Instructions

### FuseLite® SC/LC Connectors on 250-900 µm Tight-Buffered Fiber



# Visual Installation Instructions

## FuseLite® SC/LC Connectors on Buffer Tube Fan-Out Kits

### Tools Required

SC or LC FuseLite® Connectors  
 Fusion Splicer (OptiSplice® Ribbon Fusion Splicer Shown Here)  
 Connector Holder (SOC-HLD-CON-SCLC)  
 Fiber Holder (SOC-HLD-900-OS)  
 Cleaver  
 Dual-Hole Miller Tool  
 Fiber Optic Cleaning Fluid  
 Lint-Free Wipes  
 Permanent Marker

1

SC



For SC FuseLite Connector,  
Go to Step 1A

LC


OR



For LC FuseLite Connector,  
Go to Step 1B

1A


SC



Insert Rear SC Housing and Protection Sleeve  
onto the Field Fiber. Proceed to Step 2

1B

LC



Insert Rear LC Housing and Protection Sleeve  
onto the Field Fiber. Proceed to Step 2


2

900  $\mu$ m 250  $\mu$ m




Two-Hole Miller Stripper (900  $\mu$ m and 250  $\mu$ m)

3




Place a Mark  $\geq 44$  mm from the End of the Fiber

4



Strip the 900  $\mu$ m Buffer  
with Larger Notch

5



Place a Mark 4 mm Beyond the  
Buffer Tube on the 250  $\mu$ m Coating

6








Strip the 250  $\mu$ m Coating with the  
Smaller Notch Starting at the Mark

CORNING

## Visual Installation Instructions

### FuseLite® SC/LC Connectors on Buffer Tube Fan-Out Kits









CORNING



## Visual Installation Instructions




### FuseLite® SC/LC Connectors on Buffer Tube Fan-Out Kits



CORNING

## Visual Installation Instructions

### FuseLite® SC/LC Connectors on Buffer Tube Fan-Out Kits




# Visual Installation Instructions

## FuseLite® SC/LC Connectors on Buffer Tube Fan-Out Kits

32A


SC



Slide the Inner Housing Over the Dust Cap Antenna  
Align the Two Red Dots

33A


SC



Compress and  
Snap Together

34A


SC



Slide the Outer Housing  
Over the Dust Cap Antenna

35A


SC



Align SC Key Feature  
with Red Dot

36A


SC



Snap Outer Housing  
onto Inner Housing

37A


SC



Snap Off Antenna  
from Dust Cap

38A


SC



**FINISHED**  
FuseLite® SC Connector

31B


LC



Slide the Rear Housing Up to the Spring

32B


LC



Slide the Inner Housing Over  
the Dust Cap Antenna

33B


LC



Align the Two  
Trigger Components

34B


LC



Compress and  
Snap Together

35B


LC



Snap Off Antenna from Dust Cap

36B

LC



**FINISHED**  
Fuselite LC Connector



# Visual Installation Instructions

## FuseLite® SC/LC Connectors on Jacketed Cable (2.0/3.0 mm)

### Tools Required

SC or LC FuseLite® Connectors  
Fusion Splicer (OptiSplice® Ribbon Fusion Splicer Shown Here)  
Connector Holder (SOC-HLD-CON-SCLC)  
Fiber Holder (SOC-HLD-900-OS)  
Cleaver  
Dual-Hole Miller Tool  
Fiber Optic Cleaning Fluid  
Lint-Free Wipes  
Permanent Marker

1

SC



For SC FuseLite Connector,  
Go to Step 1A

LC




For LC FuseLite Connector,  
Go to Step 1B

OR

1A

SC



Insert Rear SC Housing and Protection Sleeve  
onto the Field Fiber. Proceed to Step 2

1B

LC




Insert Rear Housing onto the Field Fiber  
Proceed to Step 2

2



Ring Cut the Outer Jacket; Use Tool to Measure Length  
Remove Jacket

3




Place Fiber in Groove (20 mm Shown)

4



Mark the 900 µm Fiber at Edge of Tool for Stripping



5



Pull Cable Through the Jacket Cutter (Slices in Half)

## Visual Installation Instructions

### FuseLite® SC/LC Connectors on Jacketed Cable (2.0/3.0 mm)



## Visual Installation Instructions

### FuseLite® SC/LC Connectors on Jacketed Cable (2.0/3.0 mm)



Place Holder in Cleaver, Slide to the Right Until it Hits the Positive Stop




Gently Press Down the Lever Until it Stops, Then Release



Load the Fiber Holder into the Splicer (on the Right Side)



Fiber Should Be in "V-Groove"



Next, Select the Connector Holder and the Ferrule Assembly




Load Ferrule Assembly into the Connector Holder; Dot Facing Out




Close the Holder Arm



Load the Holder into the Splicer (on the Left Side)



Fiber Should Be in the "V-Groove"






See OptiSplice® One or OptiSplice Ribbon Fusion Splicer Instructions for Completing the Splice



## Visual Installation Instructions

### FuseLite® SC/LC Connectors on Jacketed Cable (2.0/3.0 mm)



## Visual Installation Instructions

### FuseLite® SC/LC Connectors on Jacketed Cable (2.0/3.0 mm)

**33** SC

**OR**

**LC**

For SC FuseLite® Connector, Go to Step 33A

For LC FuseLite Connector, Go to Step 33B

**33A**  
Unscrew the Boot from the Rear Housing

**34A**  
Remove Disposable Paper Tab

**35A**  
Slide Up the Rear Housing Over the Yarn and Jacket

**36A**  
Pull Remaining Yarn Through the Back of the Housing

**37A**  
Align the Two Red Dots

**38A**  
Compress and Snap Together

**39A**  
Align Jacket Halves with Back of Rear Housing

**40A**  
Slide Jacket Shoulder Sleeve Over Rear Housing


**41A**  
Slide Boot Up Over the Aramid Yarn

**42A**  
Begin to Screw on the Boot to Rear Housing (1-2 Threads)



## Visual Installation Instructions


### FuseLite® SC/LC Connectors on Jacketed Cable (2.0/3.0 mm)





## Visual Installation Instructions

### FuseLite® SC/LC Connectors on Jacketed Cable (2.0/3.0 mm)




# Visual Installation Instructions


## FuseLite® Single-Fiber Connector SRP

### Safety Precautions


#### Optical Fiber Precautions

	<b>WARNING:</b> Cleaved or broken glass fibers are very sharp and can pierce the skin or damage the eyes easily. Do not let pieces of fiber stick to your clothing or drop in the work area where they can cause injury later. Use tweezers to pick up pieces of fiber and place them on a loop of tape or approved "Fiber Optic/Sharps" disposal container.
---	--


#### Chemical Precautions

	<b>CAUTION:</b> Fiber Clean Wipes contain hydrocarbons. Apply in rooms having normal room ventilation. For prolonged and/or repeated use, gloves are recommended. Avoid eye contact. Keep away from open flames and ignition sources. If ingested, do not induce vomiting. Consult a physician. In case of eye contact, flush eyes with water for 15 minutes.
---	---


#### Personal Protection Equipment (PPE) Precautions

	<b>CAUTION:</b> Corning Cable Systems recommends the use of safety glasses (spectacles) conforming to ANSI Z87 for eye protection from accidental injury when handling chemicals, cables or working with fiber. Pieces of glass fiber are very sharp and have the potential to damage the eye.  <b>CAUTION:</b> The wearing of cut-resistant safety gloves to protect your hands from accidental injury when using sharp-bladed tools is strongly recommended. To minimize the chance of injury from sharp-bladed tools, always cut away from yourself and others. Dispose of used blades and armor scrap properly.
---	---

#### Laser Precautions

	<b>CAUTION:</b> Never look directly into the end of a fiber that may be carrying laser light. Laser light can be invisible and can damage your eye. Viewing it directly does not cause pain. The iris of the eye will not close involuntarily as when viewing a bright bulb. Consequently, serious damage to the retina of the eye is possible. Should accidental eye exposure to laser light be suspected, arrange for an eye examination immediately.
--	---

#### Cable Handling Precautions

	<b>CAUTION:</b> Fiber optic cable is sensitive to excessive pulling, bending and crushing forces. Consult the cable specification sheet for the cable you are installing. Do not bend the cable more sharply than the minimum recommended bend radius. Do not apply more pulling force to the cable than specified. Do not crush the cable or allow it to kink. Doing so may cause damage that can alter the transmission characteristics of the cable; the cable may have to be replaced.  <b>CAUTION:</b> The typical filler rod color in the cable described in this procedure is black. Careful attention should be taken to avoid accidental cutting of live buffer tubes; particularly white and black tubes. In mid-span applications, Corning Cable Systems recommends coiling all tubes and filler rods in the slack storage area of the splice closure; especially for cables with fiber counts above 96 fibers. Avoid cutting any filler rods unless necessary for storage space considerations. When in doubt regarding the buffer tube color code and filler rod replacements, contact Corning Cable Systems Engineering Services for assistance prior to cutting.  <b>WARNING:</b> Care must be taken while handling fibers during mid-span access procedures to avoid causing large deviations in optical power throughput on fibers carrying communications traffic. <b>INTERRUPTION OF SYSTEM TRAFFIC MAY RESULT FROM NEGLECT IN HANDLING OF FIBERS</b>
---	---

Corning Cable Systems LLC • PO Box 489 • Hickory, NC 28603-0489 USA  
800-743-2675 • FAX: 828-325-5060 • International: +1-828-901-5000 • [www.corning.com/cablesystems](http://www.corning.com/cablesystems)

Corning Cable Systems reserves the right to improve, enhance and modify the features and specifications of Corning Cable Systems products without prior notification. FuseLite and OptiSplice are registered trademarks of Corning Cable Systems Brands, Inc. All other trademarks are the properties of their respective owners. Corning Cable Systems is ISO 9001 certified.  
© 2012 Corning Cable Systems. All rights reserved. Published in the USA. LAN-1468-AEN / July 2012